

Service Report Sheet

SERVICE & TEST

Head Office Tel :01252 372333
 Email: enquires@chts.co.uk
 Ireland Tel :0505 23666
 Email: admin-crowthorneirl@normecgroup.com
 Scotland Tel :01236 807632
 Email: enquires@chts.co.uk

Beech House, Ancells Business Park, Fleet, Hants, GU51 2UN
 Grove Street, Roscrea, Co Tipperary, E53 PF60
 Atrium Business Centre, North Caldeen Rd, Coatbridge, ML5 4EF



REF & ISSUE QMF037 Ver 003

Call Number	14495	Contact	[REDACTED]	Cabinet Size	750mm	FC
Client	Withybush Hospital	Contact Number	N/A	Make	Labcaire Aura 250E	
Address	Hywel Dda UHB Fishgaurd Road Haverfordwest	Email Address	[REDACTED]@wales.nhs.uk	Model	Fume Cupboard	
				Recirc / Ducted	Recirculating	
Post Code	SA61 2PZ	Building / Room Number/REF	Main Theatres	Serial Number	AU250E-407	
Date	13 Nov 2025			Asset Number	N/A	
				Fan ID	N/A	
				Next Test	Nov 2026	

Fume Cupboard Service	
Cabinet Function Checks	<i>use comments section to elaborate</i>
Check Cupboard Condition	PASS
Sash: Hinge, Flaps or Wires	PASS
Check all service provisions	N/A
Check Light is operational	PASS
Check Sockets	N/A
Check Switches for functionality	PASS
Check Fan Noise/Vibration	PASS
Velocity Display Accuracy	PASS
Check Baffle fixings	N/A
Ducting Where Visible	N/A
Smoke Pencil Test	See Comments
Test Airflow/Sash Alarm	PASS
Laboratory Doors	CLOSED
Laboratory Windows	CLOSED
Capture Distance	210mm
Complete the below for SFG20 64-08	
Additional visual Checks and Maintenance	
Enclosure Integrity checks to include Main panel, sinks and other services.	N/A
Storage, underneath aperture	N/A
Lighting	N/A
Operation of warning devices	N/A
Check Air Flow Indicators	N/A
Sash Checks	N/A
All external features to include flexible couplings to duct for wear/damage	NA
Examination of electrical supply cables switch Gear and Isolators	NA
Drive Belts, for tension or wear adjust or replace as necessary	N/A

Filter Test			
Pre Filter:	CHECK	Main Filter Size:	340 x 600 x 115mm
Carbon Filter Type:	Form	Cabinet Use:	Formalin Dispensing
Filters			
Carbon	Safety	HEPA	
N/A	N/A	N/A	
N/A	N/A	N/A	
Airflow Velocity			
Aperture 1 Velocity As Found m/s			
	0.62	0.63	0.59
	0.56	0.55	0.55
Min Velocity:		0.55	Max Velocity: 0.63
Average Velocity		Aperture Size	Volume Flow Ex
0.58 m/s		0.120 m ²	0.070 m ³ /s
Aperture 2 Velocity As Left m/s			
TESTED IN ACCORDANCE WITH THE FOLLOWING			
BS 14175-4: 2004	N/A	Ducted	
BS 7989:2001	YES	Recirc	
COSHH Reg 9	N/A		
CLEAPSS G9	N/A	Schools	
SFG20 64-08	N/A	Bld Maint	
Part No Description Quantity			
no parts fitted			
no parts fitted			

Comments		
Fume Cupboard works as expected.		
Fan motor is a little noisy but operating correctly.		
No turbulence noted around sash.		
Additional Comments		
Carbon Filter last changed in 2016, recommend it is changed as soon as possible.		
Make, Model and Serial Number of Test Equipment Used on the day of test only		
Make:	Model:	Serial No
TSI	TA465-P	TA4652133008
Tested in accordance with the manufacturers instructions only when Passed		
PA		[REDACTED]
Customer Name	Customer Signature	Engineer Name
[REDACTED]	[REDACTED]	[REDACTED]